

"Trace & Repair of Commerical Gas Pipe Leak Under Car Park Ground at the Hotel"

(Photos include some parts of the process : Trace the Gas Leak, Pipe Purging, Replacement of Gas Pipes, Safety Test, Re-Connection of Gas Supply Heating Sytem and all Appliances)























"Safety Check and Service on Commercial Heating System"



"Replacement of Commercial Gas Flue on Commercial Buidling"





"Commercial Fired Pizza Oven & New Flue Installation"









Exposed Drinking Pipe Under the Ground





Commercial Catering Gas Oven Repair





New Domestic Boiler Installed





"Integrated Domestic Oven Install"





